| Certificate Number Report Reference Date | UL-CA-2212460-1 E513137-20220328 1-Apr-2022 |
|--|--|
| Issued to: | Nidec Industrial Automation India Private Ltd 45, Nagarur, Huskur Road, off Tumkur Road Bangalore, Karnataka 562162 India |
| This is to certify that epresentative samples of | JZGZ7 - Generators Certified for Canada See Addendum Page for Product Designation(s). |
| | Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate. |
| Standard(s) for Safety: | CSA C22.2 NO. 100, 7th Ed., Issue Date: 2014-07-01, Revision Date: 2017-04-01 |
| Additional Information: | See the UL Online Certifications Directory at https://iq.ulprospector.com for additional information |

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.

Bamples



Bruce Mahrenholz, Director North American Certification Program

re

(UL

Certificate Number Report Reference Date UL-CA-2212460-1 E513137-20220328 1-Apr-2022

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

| Model | Category Description |
|--|--|
| LSAP 40 C0 | Generators |
| LSAP 40 C1 | Generators |
| LSAP 40 C2, FGL10020, M1413L4, LL/LC/LCB1114 D | Generators |
| LSAP 40 C2, LSA 40 VS1, TAL 040 B, FGL10020, | Generators |
| M1413L4, LL/LC/LCB1114 D | |
| LSAP 40 D, LSA 40 VS2, TAL 040 C, FGL10030, | Generators |
| M1415L4, LL/LC/LCB1114 F | |
| LSAP 40 E, FGL10030, M1415L4, LL/LC/LCB1114 F | Generators |
| LSAP 40 E, LSA 40 S3, TAL 040 D, FGL10040, | Generators |
| M1434L4, LL/LC/LCB1114 H | |
| LSAP 40 G, LSA 40 VS1, TAL 040 C, FGL10050, | Generators |
| M1436L4, LL/LC/LCB1114 L | Vir Vir Vir Vir Vi |
| LSAP 40 H, LSA 40 M5, TAL 040 F, FGL10060, | Generators |
| M1455L4, LL/LC/LCB1114 M | |
| LSAP 42.3 B, LSA 42.3 VS1, TAL 042 A, FGL20010, | Generators |
| M1713L4, LL/LC/LLB1514 B | VUEVUEVUEVUEVI |
| LSAP 42.3 C, LSA 42.3 VS2, TAL 042 B, TAL 042 C, | Generators |
| FGL20020, FGL20030, M1717L4, LL/LC/LLB1514 F/J | \times \times \times \times \times |
| LSAP 42.3 E, LSA 42.3 S4, TAL 042 D/E, FGL20040, | Generators |
| FGL20050 | |
| LSAP 42.3 F, LSA 42.3 S5, TAL 042 E, FGL20050, | Generators |
| M1736L4, LL/LC/LLB1514 J | |
| LSAP 42.3 G, LSA 42.3 M7, TAL 042 F, FGL20060, | Generators |
| M1754L4, LL/LC/LLB1514 L | V., Y.Y., Y.Y., Y.Y. |
| LSAP 42.3 H, LSA 42.3 M8, TAL 042 G, FGL20070, | Generators |
| M1756L4, LL/LC/LLB1514 N | VII. VII. VII. VII. VI |
| LSAP 42.3 K, LSA 42.3 L9, TAL 042 H, FGL20080, | Generators |
| M1775L4, LL/LC/LLB1514 P | GGGGG |
| LSAP 42.3A | Generators |
| LSAP 42.3C | Generators |
| LSAP 42.3F, LSA 42.3 VS1, TAL 042 A, FGL20010, | Generators |
| M1713L4, LL/LC/LLB LL1514B | \times \times \times \times |
| LSAP 42.3G, LSA 42.3 VS2, TAL 042 B, FGL20020, | Generators |
| M1715L4, LL/LC/LLB LL1514D | <u> </u> |
| LSAP 42.3J, LSA 42.3 VS3, TAL 042 C, FGL20030, | Generators |
| M1717L4, M1736L4, LL/LC/LLB LL1514F | |
| LSAP 42.3K, LSA 42.3 S5, TAL 042 D, TAL 042 E, | Generators |
| FGL20040, FGL20050, M1736L4, LL/LC/LLB LL1514J | |

Bamely

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Certificate Number Report Reference Date UL-US-2213126-1 E513137-20220328 1-Apr-2022

JZGZ - Generators

Issued to: Nidec Industrial Automation India Private Ltd 45, Nagarur, Huskur Road, off Tumkur Road Bangalore, Karnataka 562162 India

This is to certify that representative samples of

Have been investigated by UL in accordance with the

See Addendum Page for Product Designation(s).

Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 1004-1, 2nd Ed., Issue Date: 2012-09-19, Revision Date: 2020-11-05, UL 1004-4, 3rd Ed., Issue Date: 2018-07-02

Additional Information: See the UL Online Certifications Directory at <u>https://iq.ulprospector.com</u> for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.

UL LLC

Bruce Mahrenholz, Director North American Certification Program

(4)

Certificate Number Report Reference Date UL-US-2213126-1 E513137-20220328 1-Apr-2022

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

| Model | Category Description |
|--|---|
| LSAP 40 C0 | Generators |
| LSAP 40 C1 | Generators |
| LSAP 40 C2, FGL10020, M1413L4, LL/LC/LCB1114 D | Generators |
| LSAP 40 C2, LSA 40 VS1, TAL 040 B, FGL10020, | Generators |
| M1413L4, LL/LC/LCB1114 D | |
| LSAP 40 D, LSA 40 VS2, TAL 040 C, FGL10030, | Generators |
| M1415L4, LL/LC/LCB1114 F | |
| LSAP 40 E, FGL10030, M1415L4, LL/LC/LCB1114 F | Generators |
| LSAP 40 E, LSA 40 S3, TAL 040 D, FGL10040, | Generators |
| M1434L4, LL/LC/LCB1114 H | |
| LSAP 40 G, LSA 40 VS1, TAL 040 C, FGL10050, | Generators |
| M1436L4, LL/LC/LCB1114 L | |
| LSAP 40 H, LSA 40 M5, TAL 040 F, FGL10060, | Generators |
| M1455L4, LL/LC/LCB1114 M | NO DE |
| LSAP 42.3 B, LSA 42.3 VS1, TAL 042 A, FGL20010, | Generators |
| M1713L4, LL/LC/LLB1514 B | |
| LSAP 42.3 C, LSA 42.3 VS2, TAL 042 B, TAL 042 C, | Generators |
| FGL20020, FGL20030, M1717L4, LL/LC/LLB1514 F/J | XXXX |
| LSAP 42.3 E, LSA 42.3 S4, TAL 042 D/E, FGL20040, | Generators |
| FGL20050 | |
| LSAP 42.3 F, LSA 42.3 S5, TAL 042 E, FGL20050, | Generators |
| M1736L4, LL/LC/LLB1514 J | |
| LSAP 42.3 G, LSA 42.3 M7, TAL 042 F, FGL20060, | Generators |
| M1754L4, LL/LC/LLB1514 L | V., V., IV., IV., IV. |
| LSAP 42.3 H, LSA 42.3 M8, TAL 042 G, FGL20070, | Generators |
| M1756L4, LL/LC/LLB1514 N | Vii, Vii, Vii, Vii, Vii, V |
| LSAP 42.3 K, LSA 42.3 L9, TAL 042 H, FGL20080, | Generators |
| M1775L4, LL/LC/LLB1514 P | |
| LSAP 42.3A | Generators |
| LSAP 42.3C | Generators |
| LSAP 42.3F, LSA 42.3 VS1, TAL 042 A, FGL20010, | Generators |
| M1713L4, LL/LC/LLB LL1514B | $\times \times \times \times$ |
| LSAP 42.3G, LSA 42.3 VS2, TAL 042 B, FGL20020, | Generators |
| M1715L4, LL/LC/LLB LL1514D | |
| LSAP 42.3J, LSA 42.3 VS3, TAL 042 C, FGL20030, | Generators |
| M1717L4, M1736L4, LL/LC/LLB LL1514F | |
| LSAP 42.3K, LSA 42.3 S5, TAL 042 D, TAL 042 E, | Generators |
| FGL20040, FGL20050, M1736L4, LL/LC/LLB LL1514J | |

Bamely

Bruce Mahrenholz, Director North American Certification Program

UL LLC